

To: Restaino, Mark[restaino.mark@epa.gov]
Cc: Galbraith, Erin[galbraith.erin@epa.gov]
From: Scott Hansen
Sent: Thur 4/25/2013 8:46:30 PM
Subject: FW: Emailing: DOC137

[Scott Hansen.vcf](#)

[IMG_0021.jpg](#)

[IMG_0015.jpg](#)

[IMG_0019.jpg](#)

[IMG_0020.jpg](#)

[DOC137.pdf](#)

Mark,

I stopped by Meleens for an inspection, no records could be located by the new manager Melissa Huff, to the best of her knowledge they were being sent to Erin. I inspected all the fills, sumps and three out of four of the dispensers. On dispenser 1, (attached photo) there was product leaking (premium) I had new manager come out and I showed her and said that it needed to be corrected ASAP.

I left a copy of the CP test and informed them to schedule a retest as required ASAP. I tested the top 9 inches of top soil and it appeared thawed.

They have an OPW 1500, and I can set up a three ring folder to help them Track tank tests by month. New manager was not familiar with system.

I stopped by Frederickson Marina and called his cell phone at 11:15 left a message about the need to inspect system by April 29, 2013.

I have not heard back.

Let's discuss.

Scott

Scott Hansen
Environmental Program Manager
Mille Lacs Band DNR/E
(320) 532-7445 business
(320) 532-7514 fax
(320) 630 2439 cell

-----Original Message-----

From: Ryan Rupp
Sent: Thursday, April 25, 2013 3:13 PM
To: Scott Hansen
Subject: Emailing: DOC137

Your message is ready to be sent with the following file or link attachments:

DOC137

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain

types of file attachments. Check your e-mail security settings to determine how attachments are handled.